

Senseair Sunrise Update

Dear Customer

As you probably already are aware of, we had to redesign the Sunrise product due to a fire in a supplier factory. We started a fast-track project to replace the component that are no longer available on the market. We will soon be ready to start the production and delivery of the new Sunrise article 006-0-0007.

Free samples to test and compare are now being distributed.

Production of the re-designed Sunrise is expected to be up and running mid-April. You are welcome to place you order on the new part number as of now and we will acknowledge based on component availability.

006-0-0007 are designed to work as drop-in replacement for the article 006-0-0002 that are now effectively End Of Life (EOL).

The only difference between the previous model and the new Sunrise we have found in our tests is a slightly higher power consumption. Please see the updated data sheet that is attached.

Again, we are sorry for any inconvenience that this may have caused.

Sincerely

Robert Jansson

Robert Jansson

COO

Senseair AB

Phone: +46 653 71 77 70 Email: info@senseair.com

www.senseair.com